

#### Moxa Inc.

Fl. 4, No. 135, Lane 235, Baoqiao Rd., Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

Tel: +886-2-8919-1230 Fax: +886-2-8919-1231 www.moxa.com

# Product Change Notification – PCN # PCN000567 9<sup>th</sup> October 2018

### Dear Valued Customer:

The purpose of this letter is to inform you that Moxa is planning to implement changes to certain products. Please review the detailed information given below to determine how these changes will affect your products and/or processes. If you have any questions regarding these changes, please contact Matthew Lee, Moxa Systems.

### **Subject:**

NOR flash memory component substitution in the UC-7101-LX / UC-7110-LX / UC-7112-LX Plus Series.

Service Level: Basic

Effective Date: 29th October, 2018

# **Model Names/ Current Version/ New Version:**

Model Name	<b>Current Version</b>	New Version
UC-7101-LX	V1.0.1	V1.0.2
UC-7101-LX/EU	V1.0.1	V1.0.2
UC-7101-LX/JP	V1.0.1	V1.0.2
UC-7101-LX/SAA	V1.0.1	V1.0.2
UC-7101-LX/US	V1.0.1	V1.0.2
UC-7101-LX/UK	V1.0.1	V1.0.2
UC-7101-T-LX/UK	V1.0.1	V1.0.2
UC-7101-T-LX/US	V1.0.1	V1.0.2
UC-7101-T-LX/SAA	V1.0.1	V1.0.2
UC-7101-T-LX/EU	V1.0.1	V1.0.2
UC-7101-T-LX	V1.0.1	V1.0.2
UC-7101-LX/CN	V1.0.1	V1.0.2
UC-7101-T-LX/CN	V1.0.1	V1.0.2

Firmware	<b>Current Version</b>	New Version
Firmware for UC-7101-LX Series	V1.3	V1.4

Form number: HQ-PD.232 Version: 1.6 Page: 1/3



#### Moxa Inc.

Fl. 4, No. 135, Lane 235, Baoqiao Rd., Xindian Dist., New Taipei City 23145, Taiwan, R.O.C.

Tel: +886-2-8919-1230 Fax: +886-2-8919-1231 www.moxa.com

Model Name	<b>Current Version</b>	New Version
UC-7110-LX	V3.0.1	V3.0.2
UC-7110-LX/EU	V3.0.1	V3.0.2
UC-7110-LX/US	V3.0.1	V3.0.2
UC-7110-LX/UK	V3.0.1	V3.0.2
UC-7110-LX/SAA	V3.0.1	V3.0.2
UC-7110-LX/JP	V3.0.1	V3.0.2
UC-7110-T-LX/EU	V3.0.1	V3.0.2
UC-7110-T-LX/SAA	V3.0.1	V3.0.2
UC-7110-T-LX/US	V3.0.1	V3.0.2
UC-7110-T-LX	V3.0.1	V3.0.2
UC-7110-T-LX/CN	V3.0.1	V3.0.2
UC-7110-LX/CN	V3.0.1	V3.0.2

Firmware	<b>Current Version</b>	New Version
Firmware for UC-7110-LX series	V4.3	V4.4

Model Name	<b>Current Version</b>	New Version
UC-7112-LX Plus	V1.0.1	V1.0.2
UC-7112-LX Plus/JP	V1.0.1	V1.0.2
UC-7112-LX Plus/EU	V1.0.1	V1.0.2
UC-7112-LX Plus/US	V1.0.1	V1.0.2
UC-7112-LX Plus/UK	V1.0.1	V1.0.2
UC-7112-LX Plus/SAA	V1.0.1	V1.0.2
UC-7112-LX Plus/CN	V1.0.1	V1.0.2

Firmware	<b>Current Version</b>	New Version
Firmware for UC-7112-LX Plus Series	V1.6	V1.7

## **Change Description:**

The original NOR flash component in the UC-7101-LX/UC-7110-LX/UC-7112-LX Plus Series has reached its end of life and will be replaced with a new component. The firmware on the UC-7101-LX/UC-7110-LX/UC-7112-LX Plus Series will also be upgraded to accommodate this change.

Form number: HQ-PD.232 Version: 1.6 Page: 2/3



#### Moxa Inc.

Fl. 4, No. 135, Lane 235, Baoqiao Rd., Xindian Dist., New Taipei City 23145, Taiwan, R.O.C. Tel: +886-2-8919-1230

Fax: +886-2-8919-1231 www.moxa.com

## Note:

Please note that the new firmware version can run on both the current and the new version of the UC-7101-LX/UC-7110-LX/UC-7112-LX Plus models, however, the old version of the firmware can only run on the current version of the UC-7101-LX/UC-7110-LX/UC-7112-LX Plus Series models.

### **Delivery Schedule:**

The substitution of the NOR flash component in the UC-7101-LX/UC-7110-LX/UC-7112-LX Plus with the new one will be implemented as a running change starting from 29<sup>th</sup> October 2018.

\_\_\_\_\_\_

Note: For questions, contact the <a href="matthew.lee@moxa.com">matthew.lee@moxa.com</a> or your regional sales contact.

Form number: HQ-PD.232 Version: 1.6 Page: 3/3