

Moxa Inc. Fl. 4, No. 135, Lane 235, Baoqiao Rd., Xindian Dist., New Taipei City 23145, Taiwan, R.O.C. Tel: +886-2-8919-1230 Fax: +886-2-8919-1231 www.moxa.com

Software Release Notification 2<sup>nd</sup> January, 2018

Dear Valued Customer:

The purpose of this letter is to inform you that Moxa is releasing new software for the ioLogik E1200 series. Please review the detailed information given below to determine how these changes will affect your products and/or processes. If you have any questions regarding these changes, please contact the person listed below for further information.

## Subject:

New firmware and utility release for the ioLogik E1200 series

Effective Date: 26th January, 2018

## **Change Description:**

Model	New Version	Release Note
ioLogik E1200	V3.0	New features or enhancements:
series firmware		<ul> <li>Added OPTIONS method for RESTful API</li> </ul>
		<ul> <li>Added quick access URI for RESTful API</li> </ul>
		<ul> <li>Added SNMP Trap Community Setting on web console</li> </ul>
		<ul> <li>Mentioned max. 16 characters on password setting page</li> </ul>
		Bugs Fixed:
		• Fixed DHCP lease time did not ask for extension when
		half of the lease time elapsed.
		<ul> <li>Closed IP forwarding function (Port 0).</li> </ul>
		<ul> <li>Closed UDP Port 161 when SNMP agent is disabled.</li> </ul>
		<ul> <li>Fixed invalid token issue on login page when using</li> </ul>
		Firefox.
		<ul> <li>Fixed invalid token issue on DO setting page.</li> </ul>
		(E1211/E1214)
		<ul> <li>Fixed invalid token issue on Modbus Address setting</li> </ul>
		page. (E1240)
		• Fixed pulse width cannot be set by MXIO Library.
		(E1242)



ioSearch	V2.0	New features or enhancements:
utility		<ul> <li>Changed EtherNet/IP per unit licensing policy to one</li> </ul>
		unit/license file only policy
		<ul> <li>Revised help file including RESTful API and EtherNet/IP</li> </ul>

## Note:

- 1. When updating firmware version V3.0 or higher, use ioSearch V2.0 or higher version to upgrade.
- 2. Update only the next or the previous released firmware version to prevent from system failure.
- 3. To avoid system failure while updating the firmware, follow the instructions given in Appendix I in ioLogik E1200 series user's manual.

## **Delivery Schedule:**

The new software is available for download from Moxa's website starting 26<sup>th</sup> January, 2018. And will be released in new products via a running change.

Submitted by: Tomson Chen, Product Manager, Moxa Automation Authorized by: Johnny Wang, Manager, Moxa Automation

Note: If you have further questions, please send an email to **tomsonpj.chen@moxa.com** or contact your regional sales representative.